



SAS Superstructure

Location: 04-SF-80-13.2 / 13.9

Client Name: CalTrans

Run date 21-Nov-14

Time 12:12 PM

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 073 Const Calendar Day: 500

Date: 21-Jan-2011 Friday

Inspector Name: Hart, Grady

Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 08:00 AM 17:00 PM Break:

Over Time:

Federal ID:

Location:

Reviewer: Shedd, Bill

Approved Date:

Status: Submit

04-0120F4
04-SF-80-13.2/13.9
Self-Anchored
Suspension Bridge

Weather

Temperature 7 AM

12 PM

4PM

Precipitation no

Condition cool morning and afternoon . Temp. 50's F

Working Day ☒ If no, explain:

Diary:

Dispute

General Comments

I inspected the Skyway (deck) of the Bay Bridge and there is now a cage (safe) ladder at the transition section of the Skyway bridge (east bond) as shown in the photo. The ladder leads to the temp tower. Also I answered emails, and worked on office reports. No know incidents to report.



Attachment



cage ladder at the end of the Skyway east bound section.